1. Community Speed Watch

12 volunteers

Valerie Clark, Janet Cox (co-ordinator), Richard Jones,
 Sue and Neil Margereson, Jane and David O'Reilly, Dave Spencer,
 Annie and Jake Waddilove, Meg White-Thompson, Mike Wyllie

POLITE NOTICE COMMUNITY SPEED WATCH AREA REDUCE YOUR SPEED

Status

- Volunteers identified and cleared by Suffolk Constabulary
- Training Video watched, agreements submitted, Roadside Training being scheduled
- Monitoring sites along The Street to be approved. First session expected in October

2. Road Markings

- Repaint gateways inc. SLOW, dragon's teeth, 30mph roundels, and solid lines
- Paint 2x 30mph roundels mid-village; exact location to be identified
- · Paint dashed lines from each gateway for 100 metres into the village

Status

- Site Visit conducted by Highways, Funding (£1,468) approval secured
- Repainting work should be scheduled for Q4-2023

Questions

- Is everyone ok with having 2x new 30mph roundels painted mid-village?
- Should we paint the Village Gates white (recommended by Highways) or leave them unchanged?

WELCORE TO HUNSTON PARAMETERS OF THE CARESULY

30

3. Tube Survey

- Tubes connected to a monitoring device and placed across the road
- Captures dates/times, no. and size of vehicles, no. of vehicles speeding
- Suggested timing of survey is 1-2 months after the road markings have been repainted and Community Speed Watch has been active
- Funding Request Funding approval is requested for £615.

4. Verge Erosion

- Asked Highways if kerbing can be installed to combat verge erosion
- In rural areas, kerbing is normally installed to direct rain water into drainage systems.
- Additional kerbing should be justified to resolve flooding or other water issues
- Recommend no further action is taken at this time



5. Other Measures to be considered

Chicanes, Speed Indicator Devices (SIDs)



